Michael O. Leavitt

Kathleen Clarke

Lowell P. Braxton Division Director

INSPECTION REPORT

DIVISION OF OIL, GAS AND MINING
1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD) Partial: Complete: XXX Exploration: Inspection Date & Time: 09/25/2001 / 8 AM-10:15 AM

Date of Last Inspection: 08/22/2001

Mine Name: Wildcat Loadout	County: Carbon	Permit Number: <u>C/007/033</u>
Permittee and/or Operator's Name: _	Andalex Resources, Inc.	
Business Address: P.O. Box 902,	Price, Utah 84501	
Type of Mining Activity: Undergrou	und Surface	Prep. Plant XXX Other
Company Official(s): Mr. Scott Di	mick, Surface Foreman	
State Official(s): Peter Hess Fed	leral Official(s): None	
Weather Conditions: <u>Clear; 60's to</u>	80's Fahrenheit	<u> </u>
Existing Acreage: Permitted 100	Disturbed <u>63.7</u> R	legraded Seeded
Status: Active XXX		

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.

DEPARTMENT OF NATURAL RESOURCES

- a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
- b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		<u>EVALUATED</u>	<u>N/A</u>	<u>COMMENTS</u>	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]	П	П	\Box
2.	SIGNS AND MARKERS	[X]			\Box
3.	TOPSOIL	[X]	\Box	\Box	\Box
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	[X]	\Box	[X]	
	b. SEDIMENT PONDS AND IMPOUNDMENTS	[X]	П	[X]	П
	c. OTHER SEDIMENT CONTROL MEASURES	[X]	П	[X]	П
	d. WATER MONITORING	[X]	\Box	[X]	\Box
	e. EFFLUENT LIMITATIONS	[X]	\Box	\Box	\Box
5.	EXPLOSIVES	\Box	[X]	\Box	
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	П	[X]		\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]	\Box	[X]	П
8.	NONCOAL WASTE	[X]	\Box	\Box	\Box
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	[X]	∐ .	[X]	\Box
10.	SLIDES AND OTHER DAMAGE	\Box	[X]	\Box	\Box
11.	CONTEMPORANEOUS RECLAMATION	\Box	[X]		
12.	BACKFILLING AND GRADING	\Box	[X]	\Box	\Box
13.	REVEGETATION	. []	[X]	П	
14.	SUBSIDENCE CONTROL	[X]	\Box	[X]	\Box
15.	CESSATION OF OPERATIONS	\Box	[X]		\Box
16.	ROADS:				
	a. CONSTRUCTION/MAINTENANCE/SURFACING	[X]	\Box	Ц	\Box
	b. DRAINAGE CONTROLS	[X]		Ц	\Box
17.	OTHER TRANSPORTATION FACILITIES	[X]	П	П	
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	\Box	П	\Box
19.	AVS CHECK (4th Quarter- April, May, June)	[X]	\Box		\Box
20.	AIR QUALITY PERMIT	[X]	\Box	\Box	\Box
21	BONDING & INSURANCE	[X]	[]	[]	[]

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: <u>C/007/033</u>

DATE OF INSPECTION: 09/25/2001

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

4A. HYDROLOGIC BALANCE: DIVERSIONS

The permittee has repaired the erosion in the bottom of the ditch joining ditches D-17 and D-17A to the 24-inch half round culvert reporting to the west side of sediment pond "F."

The permittee has removed the sediment blockage from the 12-inch CMP designated as C-20 (primary discharge culvert from sediment pond "F"). The sediment has been cleaned into the culvert as far as a shovel can reach.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The second quarter 2001 impoundment inspections were conducted by Mr. Dan Guy, Utah registered professional engineer, on 6/29/2001. There were no problems noted relative to instability or other hazards for the six UPDES sedimentation ponds, A through F. Mr. Guy also inspected the permanent impoundment and the depression area, with no problems being noted.

Today's field inspection revealed that ponds A and F contained some water; all other ponds were dry. There were no problems observed with any of the site's impoundments.

The third quarter impoundment inspections are pending.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The permittee has installed additional straw bales on the NW to SE disturbed area perimeter boundary at ASCA #2 (400 feet down channel of WCW-1).

The permittee has not replaced the straw bales at ASCA #5, but has installed a second row of bales behind those which were in need of maintenance. The new sediment control bales are pinned in place.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The permittee collected surface water samples at monitoring points WCW-1 and WCW-2 on July 10, 2001.

The permittee has completed the third quarter water monitoring requirements for the site.

The analytical results were not available for review.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The second quarter refuse pile inspection / certification was performed by Mr. Dan Guy, P.E. on June 29, 2001. There were no problems noted either by Mr. Guy or by today's field inspection.

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/033

DATE OF INSPECTION: 09/25/2001

9. PROTECTION OF FISH, WILDLIFE, AND RELATED ENVIRONMENTAL VALUES

The permittee has stored two heavy equipment batteries and two automotive batteries along with various other mining related apparatus just NNE of the main electrical substation. Mr. Dimick agreed to move these to a proper storage area or dispose of same.

14. SUBSIDENCE CONTROL

The Wildcat Loadout is a coal storage / rail loading facility only. No mining activities have ever occurred at the site either on the surface or underground. There has never been subsidence associated with the site.

Inspector's Signature:

Peter Hess #46

Date: September 25, 2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM Mike Glasson, Andalex Price Field office

O:\007033.WCL\Compliance\2001\c_0925.wpd